



**Office of the Chief Executive**

GPO Box 367, Canberra ACT 2601  
25 Constitution Avenue, Canberra ACT 2600

t +61 2 6268 4182

f +61 2 6268 5685

[www.airservicesaustralia.com](http://www.airservicesaustralia.com)

ABN 59 698 720 886

The Hon Barnaby Joyce MP  
Deputy Prime Minister  
Minister for Infrastructure and Transport  
Parliament House  
CANBERRA ACT 2601

Dear Deputy Prime Minister

**REPORT ON MOVEMENT CAP FOR SYDNEY AIRPORT**

In accordance with Section 9 of the *Sydney Airport Demand Management Act 1997*, I advise that for the quarter 1 October 2017 to 31 December 2017 there were no occasions when movements at Sydney Airport exceeded the regulated hourly maximum movement cap.

Yours sincerely

A handwritten signature in black ink, appearing to be "J Harfield", written over a large, light-colored scribble or watermark.

Jason Harfield  
Chief Executive Officer  
22 January 2018