

Office of the Chief Executive

GPO Box 367, Canberra ACT 2601 25 Constitution Avenue, Canberra ACT 2600

> t +61 2 6268 4182 f +61 2 6268 5685

www.airservicesaustralia.com

ABN 59 698 720 886

The Hon Darren Chester MP Minister for Infrastructure and Transport Parliament House CANBERRA ACT 2601

Dear Minister

REPORT ON MOVEMENT CAP FOR SYDNEY AIRPORT

In accordance with Section 9 of the *Sydney Airport Demand Management Act 1997*, I advise that for the quarter 1 April to 30 June 2017 there was one occasion when movements at Sydney Airport exceeded the regulated hourly maximum movement cap.

This occurred on 16 May 2017 in the period 8:15 – 09:15am, with 81 movements during the hour. It is the first occasion since June 2011 that the movement cap has been exceeded.

Movement cap monitoring is a manual process and we have taken steps to further minimise the risk of recurrence.

Yours sincerely

Jason Harfield

Chief Executive Officer

July 2017