

Office of the Chief Executive

GPO Box 367, Canberra ACT 2601
25 Constitution Avenue, Canberra ACT 2600

t +61 2 6268 4182

f +61 2 6268 5685

www.airservicesaustralia.com

ABN 59 698 720 886

The Hon Michael McCormack MP
Deputy Prime Minister
Minister for Infrastructure and Transport
Parliament House
CANBERRA ACT 2601

Dear Deputy Prime Minister

REPORT ON MOVEMENT CAP FOR SYDNEY AIRPORT

In accordance with Section 9 of the *Sydney Airport Demand Management Act 1997*, I advise that for the quarter 1 January 2019 to 31 March 2019 there were no occasions when movements at Sydney Airport exceeded the regulated hourly maximum movement cap.

Yours sincerely

A handwritten signature in blue ink, consisting of several loops and a long horizontal stroke, positioned over the typed name and title.

Jason Harfield
Chief Executive Officer

11 April 2019