



**Office of the Chief Executive**

GPO Box 367, Canberra ACT 2601  
25 Constitution Avenue, Canberra ACT 2600

t +61 2 6268 4182

f +61 2 6268 5685

[www.airservicesaustralia.com](http://www.airservicesaustralia.com)

ABN 59 698 720 886

The Hon Michael McCormack MP  
Deputy Prime Minister  
Minister for Infrastructure, Transport and Regional Development  
Parliament House  
CANBERRA ACT 2601

Dear Deputy Prime Minister

**REPORT ON MOVEMENT CAP FOR SYDNEY AIRPORT**

In accordance with Section 9 of the *Sydney Airport Demand Management Act 1997*, I advise that for the quarter 1 October 2019 to 31 December 2019 there were no occasions when movements at Sydney Airport exceeded the regulated hourly maximum movement limit.

Yours sincerely

A handwritten signature in blue ink, appearing to be "J Harfield". The signature is fluid and cursive, with a large loop at the beginning and a long, sweeping tail.

Jason Harfield  
Chief Executive Officer

13 January 2020