
STANDARD INSTRUMENT DEPARTURES (SID) ESSENDON EIGHT DEPARTURE (RADAR) **MELBOURNE/ESSENDON, VIC (YMEN)**

21 MAY 2020



ESSENDON EIGHT DEPARTURE (RADAR)

RWY 08

- GRAD 3.3%
- Track 077°
 At 1000FT[‡] BUT NOT BEFORE DER turn to assigned heading or track

RWY 26

- GRAD 3.3%
- Track 247°
- At 1500FT BUT NOT BEFORE DER turn to assigned heading

#CAUTION: FREEWAY AND TRAM SIGNAGE AND LIGHTING UP TO 290FT IN DEP AREA.

RWY 17

- GRAD 3.6% to 1600FT then 3.3%
- Track 166°
- At 1000FT[‡] BUT NOT BEFORE DER turn to assigned heading or track

RWY 35

- GRAD 3.3%
- Track 346°
- At 1000FT [‡] BUT NOT BEFORE DER turn to assigned heading or track

COMMUNICATIONS FAILURE PROCEDURE

On recognition of communication failure

- Squawk 7600
- Maintain last assigned vector for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE, to maintain terrain clearance, then
- Proceed in accordance with the latest ATC route clearance acknowledged.

Changes: SID INSTRUCTIONS, CHART TITLE, Editorial.

MENDP01-163

