
# STANDARD INSTRUMENT DEPARTURES (SID) ROCKHAMPTON THREE DEPARTURE (RADAR) RWY 15 & 33 ROCKHAMPTON, QLD (YBRK)

# 1 DEC 2022



# ROCKHAMPTON THREE DEPARTURE (RADAR)

# **RWY 15**

- GRAD 3.3%
- Track 148°
- AT 1300ft turn to assigned heading or track

#### **RWY 33**

- GRAD 3.4% to 2500ft, then 3.3%
- Track 328°
- AT 1300ft turn to assigned heading or track

# COMMUNICATIONS FAILURE PROCEDURE

On recognition of communications failure

- Squawk 7600
- Maintain last assigned vector for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE, to maintain terrain clearance, then
- proceed in accordance with the latest ATC route clearance acknowledged.

Changes: CORAL APP FREQUENCY, Editorial.



BRKDP01-173