
STANDARD INSTRUMENT DEPARTURES (SID) TINDAL THREE DEPARTURE (RADAR) TINDAL, NT (YPTN)

30 NOV 2023



TINDAL THREE DEPARTURE (RADAR)

RWY 14

- GRAD 3.3%
- Track 136°
- AT 1000ft but not before DER turn to assigned heading or track

RWY 32

- GRAD 3.3%
- Track 316°
- AT 1000ft but not before DER turn to assigned heading or track

COMMUNICATIONS FAILURE PROCEDURE

On recognition of Communications Failure:

- Squawk 7600
- · Maintain last assigned vector for two minutes, and
- CLIMB IF NECESSARY TO MINIMUM SAFE ALTITUDE to maintain terrain clearance, then
- Proceed in accordance with the latest ATC route clearance acknowledged

Changes: AFIS, Editorial.



