


MUNGALALU-TRUSCOTT

ELEV 180

AVFAX CODE 6914



WA
140523S
AD OPR Mungalalu North Kimberley Airport Pty Ltd, Level 1, 100
Havelock Street, West Perth, WA, 6005. Email:
truscott@mnkairport.com.au. ARO H24 08 9161 4004. Website:
www.mnkairport.com.au.

1262251E
VAR 2 DEG E

UTC +8
YTST
CERT

REMARKS
PPR.

HANDLING SERVICES AND FACILITIES
AVGAS, JET A1. Limited supply, PPR CTC AD OPR.

PASSENGER FACILITIES
WC/AC by prior arrangement.

AERODROME OBSTACLES
Primary IWI 207FT AMSL, PSN 140537.09S 1262311.30E APRX BRG 124 DEG MAG
0.4NM FM ARP. Infringes TNS by 4FT.

METEOROLOGICAL INFORMATION PROVIDED
1. TAF CAT C, METAR/SPECI.
2. AWIS FREQ 135.6 - Report faults to AD OPR.

PHYSICAL CHARACTERISTICS
12/30 126 59a PCN 5/F/A/0.73 MPa/U WID 30 RWS 90

AERODROME AND APPROACH LIGHTING
RWY 12/30 LIRL AFRU+PAL 128.0 SDBY PWR AVBL
RWY 12/30 PAPI(2) AFRU+PAL 128.0 3.0 DEG39FT SDBY PWR AVBL
RWY 12/30 PTBL(1) BY PRIOR
ARRANGEMENT

- (1) 1HR PN
- (2) Left side.

OTHER LIGHTING
TWY LGT: Blue edge.

ATS AND AERODROME COMMUNICATION FACILITIES
FIA BRISBANE CENTRE 120.75 FL330

LOCAL TRAFFIC REGULATIONS
1. On landing, roll through and use turning nodes at end of RWY. Do not turn on RWY.
2. South east apron maximum wingspan 20M for Bays 3 and 4.

CTAF - AFRU 128.0

ADDITIONAL INFORMATION
1. Model ACFT ACT WI 300M RAD of RWY 12/30 up to 400FT AGL. OPR will monitor CTAF and vacate RWY if ACFT APCH or DEP. PH AD OPR.
2. Bird and animal hazard exists.
3. RWS may be degraded due to erosion and soft soil DRG the period OCT to MAY.

CHARTS RELATED TO THE AERODROME
1. WAC 3108.
2. Also refer to AIP Departure and Approach Procedures.